

Catalog Change *Announcement*

Catalog: 2001 Torque Converter Catalog

Page: 5

Transmission Section: 4T65E - PWM Lockup

Change: C28C, C49C and C52C added to 4T65E section

4T65E - PWM Lockup

		DIA	Pilot	Hub	Mount	Spline	Part Number
		10.25"	.825"	1.787" w/ bushing	3 Pads	27	
Code: JXFM; (+2420) 4T65E Transmission - 19 Vane Stator Medium High Stall; Woven Carbon Clutch; Strategy 2							
		DIA	Pilot	Hub	Mount	Spline	Part Number
		10.25"	.825"	1.787" w/ bushing	3 Pads	27	
Code: FYHB; (+2420) 1997 3.8L Buick La Sabre Low Stall; Woven Carbon Clutch; Strategy 2							
		DIA	Pilot	Hub	Mount	Spline	Part Number
		10.25"	.825"	1.787" w/ bushing	3 Pads	27	
Code: FLHB, FLQB; (+2420) 1998-up; 3.8L Oldsmobile Intrique Low Stall; Woven Carbon Clutch; Strategy 2							
		DIA	Pilot	Hub	Mount	Spline	Part Number
		11.875"	.850"	1.787" w/ bushing	3 Pads	27	
Code: JTFM 1997-up; 3.8L Supercharged Low Stall; Woven Clutch							
		DIA	Pilot	Hub	Mount	Spline	Part Number
		11.875"	.850"	1.787" w/ bushing	3 Pads	27	
Code: JSFM 1997-up; 3.4L, 3.5L: Dual Overhead Cam Medium Stall; Woven Clutch							